



1A. Cost Center: TS1306		TAT ZONE II CONTRACT CONTRACT NO. 68-01-7368 TECHNICAL DIRECTION DOCUMENT (TDD) ECOLOGY AND ENVIRONMENT, INC.		2. No.: T 06-8709-17 TXD982305195 Amendment <u>A</u>	
1B. Account No.: TTX0507SAC					
3A. Priority <input checked="" type="checkbox"/> High <input type="checkbox"/> Medium <input type="checkbox"/> Low	4A. Estimate of Total Hours: <div style="background-color: black; color: red; padding: 5px; display: inline-block;">(b) (4)</div>	5A. EPA Site Name: Grant Rd. Drum Site		7. Completion Date: 11/27/87	
		5B. SSID No.: N/A	5C. City/County/State: Houston/Harris/TX		8. Reference Info: <input type="checkbox"/> Yes <input type="checkbox"/> Attached <input checked="" type="checkbox"/> No <input type="checkbox"/> Pick-up
3B. Key EPA Contact: Name: Staves Phone: 655-2270		4B. Overtime Approved: <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No		6. Source of Funds: <input type="checkbox"/> Other _____ <input checked="" type="checkbox"/> CERCLA <input type="checkbox"/> 311 <input type="checkbox"/> UST	
8A. Subtask Code:					
9. Type of Activity: <div style="display: flex; justify-content: space-between;"> <div style="width: 30%;"> CWA-311 <input type="checkbox"/> SPCC <input type="checkbox"/> On-Scene Monitoring <input type="checkbox"/> Spill Clean-up Funded </div> <div style="width: 30%;"> CERCLA <input checked="" type="checkbox"/> Site Assessment <input type="checkbox"/> Removal Funded <input type="checkbox"/> Removal PRP (AO/CO) <input type="checkbox"/> On-Site Monitoring </div> <div style="width: 30%;"> AS SPECIFIED ABOVE <input type="checkbox"/> Special Project <input type="checkbox"/> Analytical Project <input type="checkbox"/> TITLE III <input type="checkbox"/> UST <input type="checkbox"/> FEMA </div> <div style="width: 30%;"> <input type="checkbox"/> Quality Assurance <input type="checkbox"/> Training <input type="checkbox"/> Program Management <input type="checkbox"/> Technical Assistance <input type="checkbox"/> Information Management </div> </div>					
10. General Task Description: <u>Perform site assessment to determine removal potential</u>					11. Desired Report Form: <input checked="" type="checkbox"/> Formal Report <input type="checkbox"/> Letter Report <input type="checkbox"/> Formal Briefing <input type="checkbox"/> Other (Specify) _____
12. Specific Elements: <u>TDD Amended to extend completion date, and change in scope.</u> <u>Original TDD Specific Elements:</u> 1) Follow established guidelines during all phases of site assessment 2) Review previous undelivered TAT report 3) Open and test all drums using the "HAZ CAT" methodology 4) Compile samples from drums with similar characteristics into five (5) composite samples for priority pollutant analyses, transport samples to EPA Houston Lab. 5) Perform other duties as assigned by OSC <u>Amended elements:</u> 1) "HAZ CAT" deleted from task 2) Obtain four (4) grab samples from open containers and transport samples to EPA Houston Lab. 3) Develop and present elements for draft Action Memo with formal report.					
14. Authorizing DPO:  <div style="text-align: center;">(Signature)</div>					15. Date: 11/19/87
16. Received by: <input checked="" type="checkbox"/> Accepted <input type="checkbox"/> Accepted with Exceptions (Attached) <input type="checkbox"/> Rejected <div style="text-align: center;">  (TATL Signature) </div>					17. Date: 11-23-87

Distribution:

Sheet 1 White Sheet 2 Blue Sheet 3 Green Sheet 4 Canary Sheet 5 Pink Sheet 6 Goldenrod	DPO Copy TATL Copy ZPM Copy PO Copy CO Copy DPO Original (Unsigned by TATL)
---	--

T0070:

B. Marquaccio